




**Ko mēs 2026. gadā esam izdarījuši citādi, un ko no tā iegūst
Latvijas atkritumu apsaimniekotājs?
12+ mēneši → 6 – 7 mēneši**





ALWARK Latvija 2026



- Reģionālie servisa centri: Ventspils, Saldus, Skrunda, Kuldīga, Jelgava, Smiltene, Cesvaine, Daugavpils
- 34 mobilās servisa vienības
- Servisa atbalsts: 24/7


"Terberg Connect" – Telemātikas un attālināta diagnostikas sistēma

Filter

> Alwark Latvia (S)



Current location



[Trips](#) 

Vehicle ID
 319881

Lift type
 OmniTRADE

Connectivity
 Connected

Current location
Stabu iela, Rīga

Depot
 To Be Assigned

Signal strength
 Excellent

Last seen (CEST)
 09/09/2026 14:46:42 

Statistics

Shift counter 2-Wheel Bin
36

Total Counter 2-Wheel Bin
43238

Compaction Cycles for Shift
65

Axle Weight (kg)

Shift Counter 4-Wheel Bin
189

Total Counter 4-Wheel Bin
123401

Total Compaction Cycles
171456

Distance Trip
0 Km

Shift Time of Operation
11:07:00

Total Amount of Lifts
166639


Tailgate Cycles for Shift

Total Distance
0 Km

Collection Time for Shift
01:15:00

Total Operating Hours
8226

Total Tailgate Cycles
0



  Show more information

Chair
Position
28.1%

Speed
output
0.0%

Up
Down

Left bin counter total
19124

Right bin counter total
23858

Sensors

- | LH | RH |
|-------------------------------------|--------------------------|
| ☐ | ☐ |
| N1 start sensor | |
| ☐ | ☐ |
| N6 bin present | |
| ☐ | ☐ |
| N7 bin pickup arm open | |
| ☐ | |
| N11 4-Wheel detection | |
| ☒ | |
| Hopper plate switch | |

Status inputs

- ☒ Emergency stop
- ☐ Truck in motion
- ☒ Neutral gear
- ☒ System ready
- ☐ Packer inside collision zone. Interlock
- ☒ Footboards clear

Status outputs

- ☐ Low chair warning
- ☐ Oil request
- ☐ Start packer cycle
- ☐ Bin / Bin lift inside collision zone. Interlock

D2  Gear selected

0  Accelerator 1

 Footbrake status

 Handbrake status

Axle	Weight
1	0 Kg
2	0 Kg
3	0 Kg
4	0 Kg
Total weight	0 Kg



Chassis Comms OK 

RPM  1379

 Speed  14 Km/h

Gear engaged  D2

Neutral status 

Reverse status 

PTO1 engaged 

  Show more information

Request to chassis

-  RPM request
-  Throttle request
-  RPM limit request
-  Brake request


Response from chassis

-  RPM 1379 RPM
-  Gear selected D2
-  Gear engaged D2
-  Handbrake status

Response from chassis

-  Fuel level 0 %
-  Fuel trip 0 L
-  Fuel total 0 L
-  Chassis Comms OK

DISCHARGE



  Show more information

Physical Inputs

-  Discharge door up button OK
-  Discharge door down button OK
-  Discharge door encoder OK
-  Ejector in button OK
-  Ejector out button OK
-  Ejector sensor in cabin
-  Access door sensor
-  Discharge door position 897

Non-Physical Inputs


-  Discharge door up from cabin
-  Discharge door down from cabin
-  Ejector in from cabin
-  Ejector out from cabin
-  RPM 524 RPM

Outputs

-  Front venting
-  Rear venting
-  Lifter venting
-  Discharge door up coil
-  Discharge door down coil
-  Ejector in coil
-  Ejector out coil
-  Barrier retention 6 mA

Calculated States

-  Collector in emergency status
-  Tip status
-  Drive status
-  Delivery from external buttons
-  In locks
-  Discharge door 1m zone
-  Discharge door open
-  Discharge door on top



Zināšanas un kompetence



Alwark grupas uzņēmuma pārstāvētie ražotāji

HITACHI

Reliable solutions



KONECRANES
Lifting Businesses™



Linde Material Handling

Linde



BUCHER
municipal



Jauns sadarbības partneris no 2025. gada (karjeru tehnika):



Hitachi mainās. Mainās tehnoloģijas. Mainās spēles noteikumi. LANDCROS.

LAND = ZEME — tur, kur mēs strādājam

C = **Customer** — KLIENTS ir centrā

R = **Reliable** — UZTICAMĪBA ir pamats

O = **Open** — ATVĒRTĪBA rada iespējas

S = **Solution** — RISINĀJUMI veido nākotni



Hitachi – Landcros Construction Machinery

HITACHI

Reliable solutions



Frontālie iekrāvēji



Riteņu ekskavatori



Kāpurķēžu ekskavatori



Mini ekskavatori

Fuchs materiālu kraušanas tehnika (17 t. – 150 t.)



Alwark klientu diena 2026 / 24.septembris



Paldies!



ALWARK
INDUSTRIAL MACHINERY